

# Tracer

## General Principles to Observe

Guarantee the existence of a protective presser, preferably transparent, in order to fixate the wooden piece that is going to be cut, for avoiding contact with the saw and observing the cutting line.

Guarantee that the saw is in the table, in resting position.

Guarantee the functioning of the tracer only after conditioning simultaneously the bimanual command.

Be attentive to the dangerous part of the machine, the cutting zone.

Always that is justified use a laser line marker, in particular, during the cut of borders/extremities of the piece.

Use pressers to fixate the large dimension pieces in the working table, in order to guarantee that the hands are away from the machine's operation area.

Guarantee the location of an effective aspiration system in order to prevent wood dust in the work place.

Use table extensions for support in order to place the pieces.

## Risk Factors

**Collision as a result of moving objects (including fragments and particles)**

Protection from wood particles and/or residues during or in the cutting process. Rejection of the piece of wood during the cut.

**Exposure to noise**

**Exposure to chemical agents**

Dust resulting from cutting the materials.

**Crushing/getting between an immobile object and another moving one**

Crushing the hands resulting from the falling of the machine's protective presser.

**Falling objects**

Falling objects in the course of the maintenance/cleaning task.

**Excessive effort**

Effort resulting from the elevation and manual movement of pieces of wood.

## Individual Protection Equipment

Hearing protectors

Safety gloves

Protective shoes