

Blade Sewer

General Principles to Observe

Guarantee that the installed protectors and protective devices are functioning in a way to avoid access to dangerous zones in the machine.

Avoid direct contact with the machine's hot surfaces, especially where the thread of the thermo fusil suffers from heating.

Avoid a bad posture or flexing of the column during the task of sewing the sheets. When possible introduce periodic pauses.

Risk Factors

Crushing/getting between an immobile object and another moving one

Hand placing in the machine tracer.

Excessive effort

Effort resulting from the adopted position during the work execution.

Contact with igniting objects or substances

Hand contact with the resistance used for the heating of the thermo fusil

Deficient lighting

Exigency of visual sharpness, which can be jeopardized by low illumination levels.

Individual Protection Equipment

Safety gloves for mechanical action

Protective shoes

